

0022875

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET

25X1

COUNTRY Poland

REPORT NO.

25X1

SUBJECT Situation at the Gdynia Repair Shipyard

DATE DISTR.

4 March 1954

25X1

NO. OF PAGES

2

DATE OF INFO.

REQUIREMENT NO.

25X1

PLACE ACQUIRED

REFERENCES

25X1

Shortages of materials.

1. The situation in the Repair Shipyard in Gdynia in regard to shortages of materials has worsened. The most acute shortages are of cables and electric wires, either rubber or lead insulated. Electric bulbs, supplied by Polish producers, were rejected by the technical control commission because the electric current passes through the insulator in the bulb necks. Most of the electric sockets (oprawki) and switches (kontakty) supplied are unfit because of faulty production.

25X1

Increased control in use of non-ferrous metals.

3. Due to the continuous shortage of non-ferrous metals, stricter control of their use has been enforced. Allocations of these metals are limited to the barest essentials for completing an order. Due to errors made in calculations, deliveries are often insufficient, and the red tape through which each application for non-ferrous metals passes in order to receive the correct amount, slows down production considerably.

Floating docks.

4. The two small floating docks allocated to the shipyard are not in use because they need a complete overhaul. This cannot be undertaken since the material for the repair, which was ordered in May 1953, has not yet been delivered.

SECRET

25X1

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		AEC		ORR	Ev	X		
-------	---	------	---	------	---	-----	---	-----	--	-----	--	-----	----	---	--	--

(Note: Washington Distribution Indicated By)

SECRET

25X1

- 2 -

Repairs to fishing craft.

5. Fishing craft units which arrive for overhaul or minor repairs are not attended to because of the lack of materials and because all effort is concentrated on overhaul of merchant fleet units.

Shipyard personnel.

6. Relations between workers, senior leaders, and leaders are very strained because the key post men tend to throw the blame for delay in production on the laziness of workers rather than on lack of materials. The workers are discouraged, and openly boycott many regulations, especially all kinds of meetings and political meetings because these take them off work and lessen their daily earnings.

SECRET

25X1